

uCables.com

Tecnologias de diagnostico y reparacion de automoviles

Mitsubishi OBD-II Trouble codes

Code	Description
P1103	Turbocharger Wastegate Actuator.
P1104	Turbocharger Wastegate Solenoid.
P1105	Fuel Pressure Solenoid.
P1300	Ignition Timing Adjustment circuit.
P1400	Manifold Differential Pressure Sensor circuit.
P1500	Alternator FR Terminal circuit.
P1600	Serial Communication Link.
P1715	Pulse Generator Assembly.
P1750	Solenoid Assembly.
P1751	A/T Control Relay.
P1791	Engine Coolant Temperature Level Input circuit.
P1795	Throttle Position Input circuit to TCM.